#7536

Fall Creek Regional Waste District 9378 S 650 W, P.O. Box 59, Pendleton, IN 46064 765-778-7544

Agreement for Sanitary Sewer Service

This Agreement made and entered into this _ Regional Waste District ("District") and	Arbor Homes ("Applicant") rega	
provision of sanitary sewer service, and the assign	Arbor Homes ("Applicant") rega	rding the
facilities for the premises located at Maplewood	d @ Huntzinger Farms Lot 128	·
Street Address: 83 WINDING	BROOK WAY	
Now therefore, the parties, in consideration receipt and sufficiency of which is hereby acknown		ent, the
before backfilling and final connection is provision will cause all lines and appurter Applicant's expense.	District must accept and approve all work and made to the sewer mains. Any violation of this tances in violation to be removed and replaced	l materials is d at the
inspect, repair, or replace any equipment has an impact on said service.	pon the Applicant's premises at all reasonable used in connection with the District's service	or which
failure to pay any rate charge or fee may termination of service to the property, the	monthly user rates, capacity charges, and tap esult in a lien against the property and/or the cost of which will be borne by Applicant, inc	
unless said damages are due to default, ne	ny damages as a result of any failure to supply glect or culpability on the part of the District. iin three hundred (300) feet of the property lin	
The Applicant and District agree that the concerns the property and the terms of thi	provision of sanitary sewer service touches and a Agreement bind the District and Applicant a representatives, successors, agents, attorneys,	and their
The parties hereto have read and fully undersprovisions.	and the above provisions and agree to comply	with said
FALL CREEK REGIONAL WASTE DISTRICT	APPLICANT,	
Signature	Signature	
STATE OF INDIANA)) SS:		
COUNTY OF MADISON)		
SUBSCRIBED and sworn to before me this _	day of, 20	
My Commission Expires:	Signature	
	Printed	
	Notary Public	
************	Resident of County	/ •
nspector DN Date Inspected 1-18-23		1
Reason for Rejecton	Approved Rejected	
	Approved Rejected	
Size Pipe 74 35		
Basement <u>Yes No</u> Sump Pump <u>Yes No</u>		North
Downspout to Ground <u>Yes No</u>		
Septic Tank Pumped & Filled Yes No Contractor DR WATER A	Danne	
Special Conditions	3,000,0	
Existing Home New Construction	4 ~ 4	
	1 picture	h d
	ather	Ne()



