

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

22-02603.00

Specifics.

Permit No.		Date 1-22-91
Permit Void 90 days		
Owner Name		
Property Address	8759	SURREY DR P.O. BOX , IN Zip Code 46064
Lot # 83	3	P.O. Box
Town PENI	DIETON	, IN Zip Code 46064
Phone		Water Meter "
\$ 500.00	Tap on Fee Pai	
2500		
\$ 25.00	Inspection fee	e paid
Waste District Sewer Residential X , C	System for the commercial	r connection to the Fall Creek Regional e above listed property - Permit Type: _, Industrial, or Governmental/ mation
District Ordinance a Acceptance and appro authorized represent to the main sewer li	s described in val must be mad ative before banes. Any viola appurtenances i	shall conform to the standards of the Ordinance 84-2 and 84-3 as amended. de by the District inspector or his duly ackfilling and final connection is made ation of applicable regulations will in violation to be removed and replaced
approval of material	s, and installa	District is responsible for the inspection, ation techniques only. All costs for liabilities resulting from same is the y owner.
I have read and comply by said provi	Musty	and the above provisions and agree to S) SIGNATURE
/ *************	*****	*********
	INSF	PECTOR TIM
	-91	1
Date inspected 1-29	Approved	Rejected
		Rejected
		Rejected
Reason for rejection		Approved Rejected
Reason for rejection Date reinspected		
Reason for rejection Date reinspected Notes: Size Pipe	"	
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe	S15/235	
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No	SDR35	
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Sump Pump Yes No	SDR35	
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Sump Pump Yes No Downspout to Ground Yes	SIDP35	Approved Rejected
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Sump Pump Yes No Downspout to Ground Yes Septic Tank Pumped &	SDP35 Yes No filled Yes N	Approved Rejected
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Sump Pump Yes No Downspout to Ground Yes Septic Tank Pumped & Contractor	SDP35 Yes No filled Yes N	Approved Rejected
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Sump Pump Yes No Downspout to Ground Yes Septic Tank Pumped & Contractor	SDP35 Yes No filled Yes N	Approved Rejected
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Sump Pump Yes No Downspout to Ground Yes Septic Tank Pumped & Contractor	SDP35 Yes No filled Yes N	Approved Rejected
Date inspected 1-29 Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Downspout to Ground Y Septic Tank Pumped & Contractor Bolton Special Conditions	SDP35 Yes No filled Yes N	Approved Rejected
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Basement Yes No Sump Pump Yes No Downspout to Ground Yes Septic Tank Pumped & Contractor	SDP35 Yes No filled Yes N	Approved Rejected