

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

220259700

Permit No.	Date	
Permit Void 90 days from Date	of Issuance	
Owner Name Lyle Sh	MEY	
Property Address 8762	CARRIGE LANE Pendleton	
	P.O. Box	
	, IN Zip Code	
	Water Meter No "	
r = 02		
\$ Tap on Fe	ee Paid	
\$ 2500 Inspectio	on fee paid	
Waste District Sewer System fo	Application is hereby made for connection to the Fall Creek Regional te District Sewer System for the above listed property - Permit Type: idential, Commercial, Industrial, or Governmental/titutional	
All workmanship and materials shall conform to the standards of the District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced at the owners expense.		
approval of materials, and ins materials and installation and sole responsibility of the pro	Waste District is responsible for the inspection, stallation techniques only. All costs for d any liabilities resulting from same is the operty owner. derstand the above provisions and agree to	
APPLIC	CANT(S) SIGNATURE	

Date inspected 11-8-91 Appr		
	INSPECTOR BEN Rejected	
	INSPECTOR BEN Rejected	
Reason for rejection	INSPECTOR BEN Rejected	
Date reinspected	INSPECTOR BEN Rejected	
Reason for rejection Date reinspected Notes: Size Pipe 6 " Type Pipe 700 Basement Yes No 6 Sump Pump Yes No 6	INSPECTOR BEN Rejected	
Reason for rejection Date reinspected Notes: Size Pipe	INSPECTOR BEN Rejected Approved Rejected	
Date reinspected Notes: Size Pipe Type Pipe Reason for rejection "" Type Pipe Type Pipe No X Sump Pump Yes No X Downspout to Ground Yes X No Septic Tank Pumped & filled Ye	INSPECTOR BEN Rejected Approved Rejected	
Date reinspected Notes: Size Pipe Type Pipe Type Pipe Sump Pump Yes Downspout to Ground Yes X No Septic Tank Pumped & filled Ye Contractor M. Six E	INSPECTOR BEN roved Rejected Approved Rejected	
Reason for rejection Date reinspected Notes: Size Pipe	INSPECTOR BEN roved Rejected Approved Rejected	
Reason for rejection Date reinspected	INSPECTOR BEN roved Rejected Approved Rejected	
Reason for rejection Date reinspected Notes: Size Pipe Type Pipe Type Pipe Basement Yes No X Sump Pump Yes No X Downspout to Ground Yes X No Septic Tank Pumped & filled Ye Contractor M. Sin E	INSPECTOR BEN roved Rejected Approved Rejected	