add order on file

F C A W CLEAN TOMORROW TODAY!

FALL CREEK REGIONAL WASTE DISTRICT

Box 44, Pendleton, Indiana 46064

220261100

Robert Taylor Spec Home

Nº 001855	
APPLICATION FOR SEWER PERMIT	
Permit No. Date 7/2/92	
Permit Void 90 days from Date of Issuance	
Owner Name	
Property Address 8765 Carriage Rane Lot # 79 P.O. Box Town Penalleton, IN zip Code 46064	
Lot # P.O. Box	
Town Yendleton, IN zip Code 46064	
Phone Water Meter "	
\$\frac{350.00}{25.00}\$ Tap on Fee Paid \(\rho d\) only \(375.00\) \$\frac{25.00}{100}\$ Inspection fee paid	
Application is hereby made for connection to the Fall Creek Regional Waste District Sever System for the above listed property - Permit Type: Residential, Commercial, Industrial, or Governmental/ Institutional User Information	
All workmanship and materials shall conform to the standards of the District Ordinance as described in Ordinance 84-2 and 84-3 as amended. Acceptance and approval must be made by the District inspector or his duly authorized representative before backfilling and final connection is made to the main sewer lines. Any violation of applicable regulations will cause all lines and appurtenances in violation to be removed and replaced at the owners expense.	
The Fall Creek Regional Waste District is responsible for the inspection, approval of materials, and installation techniques only. All costs for materials and installation and any liabilities resulting from same is the sole responsibility of the property owner.	
I have read and fully understand the above provisions and agree to comply by said provisions.	
APPLICANT(S) SIGNATURE	
APPLICANT(S) SIGNATURE ***********************************	

Time Inspected 9-2-92 Approved Rejected Reason for rejection	
TIM Date inspected 9-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6" "	
TIME Date inspected 9-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected	rth
Date inspected 9-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6" " " " " " " " " " " " " " " " " " "	rth
Date inspected 7-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6" " " " " " " " " " " " " " " " " " "	rth
Date inspected 7-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6" " Type Pipe PC SDr35 Basement Yes No	Prth
Date inspected 9-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe Puc SDr35 Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No	rth
Date inspected 9-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe C SDr35 Basement Yes No Downspout to Ground Yes No	rth
Date inspected T-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PC SD 35 Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor Brown Brothers Special Conditions Very Neat	rth
Date inspected 9-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe USD 35 Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor Brown Brothers	rth
Date inspected T-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PC SD 35 Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor Brown Brothers Special Conditions Very Neat	rth
Date inspected T-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PC SD 35 Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor Brown Brothers Special Conditions Very Neat	rth
Date inspected T-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PC SD 35 Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor Brown Brothers Special Conditions Very Neat	rth
Date inspected T-2-92 Approved Rejected Reason for rejection Date reinspected Approved Rejected Notes: Size Pipe 6 " Type Pipe PC SD 35 Basement Yes No Sump Pump Yes No Downspout to Ground Yes No Septic Tank Pumped & filled Yes No Contractor Brown Brothers Special Conditions Very Neat	rth