			1.0	55 200
			1	502988
	APPLICATION FOR	SEWER PERMIT	1 12	Nº 001097
Permit No.	I	Date 12/	31/85	
Permit Void 90 days f	rom Date of Iss	uance	/	
Owner Name	M. GARI	Ale	. /	
Property Address	10 WAST	DROADU	AY	
Lot #		P.O. Box	thould	
Town UGHLA	1/1	IN Zip Code Water Meter	70070	
Phone 480-64				
\$_/3000	Tap on Fee Paid			
\$ 00 00	Inspection fee]	paid		
Application is h	nereby made for	connection to	the Fall Creek	Regional
Waste District Sewer Residential, Co	ommercial X,	Industrial	, or Governm	ental/
Institutional	. User Informa	tion		·
All workmanship	and materials s	hall conform to	o the standards	of the
District Ordinance as Acceptance and approx	val must be made	by the Distri	ct inspector or	his duly
authorized representa	ative before back	kfilling and f	inal connection	is made
to the main sewer lin cause all lines and a	appurtenances in	violation to	be removed and	replaced
at the owners expense				
The Fall Creek	Regional Waste D	istrict is res	ponsible for th	ne inspection,
approval of materials	s, and installat	ion techniques	only. All cos	sts for
materials and instal. sole responsibility of			ditting riom san	ie is the
T have read and	fully understan	d the above pr	ovisions and ac	ree to
comply by said provis	sions.			
Martha C	alinan			
****				****
Date inspected 2/6	INSPE	CTOR ADDUG	Dejected	
Date inspected 2/6	Approved _	V	Rejected	
Reason for rejection				
Date reinspected		Approved	Rejected	
Notes: Size Pipe 6 Type Pipe PV.C	2			
Basement Yes No				
Sump Pump Yes No				
Downspout to Ground				
Septic Tank Pumped &	1/11	K	\sim	
Contractor Luis	Vastoria		9	
Guardal Ganditiana				
Special Conditions	roi) il TA	-		