

City/Utility: Oliver Springs



RYE
ENGINEERING PLC

LEAK REPORT

Date: 3-17-20

Crew Chief: ☒ Sheppard ☐ Simmons

Leak #: 15

☐ Spears ☐ Moody

Street Address: 142 Sleepy Hollow

Type of Leak:	Size:	Material:
Meter ☐	5/8" ☐ 8" ☐ 30" ☐	Poly ☐
Meter Yoke ☐	3/4" ☐ 10" ☐ 36" ☐	Copper ☐
Service Line ☐	1" ☐ 12" ☐ Other ☐	Galvanized ☐
Valve ☐	2" ☐ 16" ☐	PVC ☐
Fire Hydrant ☐	3" ☐ 18" ☐	A/C ☐
Main Line ☐	4" ☐ 20" ☐	Cast Iron ☐
Other: ☐	6" ☐ 24" ☐	Ductile Iron ☐
		Other: ☐

Rating (1-5): 4

☐ Blue Dot on Box ☐ Blue X on Leak Location

Notes: Blue Arrow pointing Tow Leak

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day	
1	•	400	
2	•	3,000	
3	•	8,000	
4	•	15,000	
5	Severe Leak - Repair as soon as possible (20,000+ per day)		