


City/Utility: Oliver Springs



LEAK REPORT

Date: 3-17-20

Crew Chief: ☒ Sheppard

Simmons ☐

Leak #: 16

☐ Spears

Moody ☐

Street Address: 313 Ridge View

Type of Leak:

Meter ☐
Meter Yoke ☐
Service Line ☒
Valve ☐
Fire Hydrant ☐
Main Line ☐
Other: _____

Size:

5/8" ☐ 8" ☐ 30" ☐
3/4" ☒ 10" ☐ 36" ☐
1" ☐ 12" ☐ Other ☐
2" ☐ 16" ☐
3" ☐ 18" ☐
4" ☐ 20" ☐
6" ☐ 24" ☐

Material:

Poly ☒
Copper ☐
Galvanized ☐
PVC ☐
A/C ☐
Cast Iron ☐
Ductile Iron ☐
Other: _____

Rating (1-5): 2

☐ Blue Dot on Box

☐ Blue X on Leak Location

Notes: Blue Arrow pointing to Leak
Leak is at Main Line

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day	
1	•	400	
2	•	3,000	
3	•	8,000	
4	•	15,000	
5	Severe Leak - Repair as soon as possible (20,000+ per day)		