

City/Utility: Oliver Springs



RYE
ENGINEERING PLC

LEAK REPORT

Date: 3-18-20

Crew Chief:

☒

Sheppard

Simmons

☐

Leak #:

18

☐

Spears

Moody

☐

Street Address:

448 Oak Circle

Type of Leak:

Meter ☐

Meter Yoke ☐

Service Line ☐

Valve ☐

Fire Hydrant ☐

Main Line ☒

Other:

Size:

5/8" ☐

8" ☐

30" ☐

3/4" ☐

10" ☐

36" ☐

1" ☐

12" ☐

Other ☐

2" ☒

16" ☐

3" ☐

18" ☐

4" ☐

20" ☐

6" ☐

24" ☐

Material:

Poly ☐

Copper ☐

Galvanized ☒

PVC ☐

A/C ☐

Cast Iron ☐

Ductile Iron ☐

Other:

Rating (1-5):

4

☐

Blue Dot on Box

☒

Arrow pointing to Leak location
~~Blue X on location~~

Notes:

This is calculated at 60 PSI:

Leak Location Sketch:

This is calculated at 60 PSI			
Rating	Pipe Leak Size	Gallons Lost/Day	
1	•	400	
2	●	3,000	
3	●	8,000	
4	●	15,000	
5	Severe Leak - Repair as soon as possible (20,000+ per day)		