


City/Utility: Oliver Springs



LEAK REPORT

Date: 3-18-20

Crew Chief: ☒ Sheppard

☐ Simmons

Leak #: 21

☐ Spears

☐ Moody

Street Address: Intersection of Oliver and England

Type of Leak:	Size:	Material:		
Meter ☐	5/8" ☐	8" ☐	30" ☐	Poly ☐
Meter Yoke ☐	3/4" ☐	10" ☐	36" ☐	Copper ☐
Service Line ☐	1" ☐	12" ☐	Other ☐	Galvanized ☒
Valve ☐	2" ☒	16" ☐		PVC ☐
Fire Hydrant ☐	3" ☐	18" ☐		A/C ☐
Main Line ☒	4" ☐	20" ☐		Cast Iron ☐
Other: _____	6" ☐	24" ☐		Ductile Iron ☐
				Other: _____

Rating (1-5): 3

☐ Blue Dot on Box

☒ Blue X on Leak Location

Notes:

Blue X on Main Line Blue X on
The leak. Intersection The leak is on
Oliver

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day	
1	•	400	
2	•	3,000	
3	•	8,000	
4	•	15,000	
5	Severe Leak - Repair as soon as possible (20,000+ per day)		