


City/Utility: Oliver Springs



LEAK REPORT

Date: 3-19-20

Crew Chief: ☒ Sheppard ☐ Simmons
☐ Spears ☐ Moody

Leak #: 28

Street Address: ~~A-1118~~ 4360? E Spring Street DWE Excavating

Type of Leak:	Size:	Material:
Meter ☐	5/8" ☐ 8" ☐ 30" ☐	Poly ☒
Meter Yoke ☐	3/4" ☒ 10" ☐ 36" ☐	Copper ☐
Service Line ☒	1" ☐ 12" ☐ Other ☐	Galvanized ☐
Valve ☐	2" ☐ 16" ☐	PVC ☐
Fire Hydrant ☐	3" ☐ 18" ☐	A/C ☐
Main Line ☐	4" ☐ 20" ☐	Cast Iron ☐
Other:	6" ☐ 24" ☐	Ductile Iron ☐
		Other:

Rating (1-5): 3

☐ Blue Dot on Box

☐ Blue ~~X~~ on Leak Location Arrow pointing to leak location

Notes:

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day	
1	•	400	
2	•	3,000	
3	•	8,000	
4	•	15,000	
5	Severe Leak - Repair as soon as possible (20,000+ per day)		