


*Oliver Springs*

City/Utility: \_\_\_\_\_



## LEAK REPORT

Date: 3-19-20

Crew Chief: ☒ Sheppard ☐ Simmons

Leak #: 32

☐ Spears ☐ Moody

Street Address: 1127 Warden Road

Type of Leak:	Size:	Material:
Meter <input type="checkbox"/>	5/8" <input type="checkbox"/>	Poly <input checked="" type="checkbox"/>
Meter Yoke <input type="checkbox"/>	3/4" <input checked="" type="checkbox"/>	Copper <input type="checkbox"/>
Service Line <input checked="" type="checkbox"/>	1" <input type="checkbox"/>	Galvanized <input type="checkbox"/>
Valve <input type="checkbox"/>	2" <input type="checkbox"/>	PVC <input type="checkbox"/>
Fire Hydrant <input type="checkbox"/>	3" <input type="checkbox"/>	A/C <input type="checkbox"/>
Main Line <input type="checkbox"/>	4" <input type="checkbox"/>	Cast Iron <input type="checkbox"/>
Other: _____	6" <input type="checkbox"/>	Ductile Iron <input type="checkbox"/>
	8" <input type="checkbox"/>	Other: _____
	10" <input type="checkbox"/>	
	12" <input type="checkbox"/>	
	16" <input type="checkbox"/>	
	18" <input type="checkbox"/>	
	20" <input type="checkbox"/>	
	24" <input type="checkbox"/>	
	30" <input type="checkbox"/>	
	36" <input type="checkbox"/>	
	Other <input type="checkbox"/>	

Rating (1-5): 3

☐ Blue Dot on Box

☐ Blue X on Leak Location *Arrow pointing to location*

Notes: \_\_\_\_\_

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day	
1	•	400	
2	●	3,000	
3	●	8,000	
4	●	15,000	
5	Severe Leak - Repair as soon as possible (20,000+ per day)		