

City/Utility: Oliver Springs



RYE
ENGINEERING PLC

LEAK REPORT

Date: 8-19-20

Crew Chief:

☒ Sheppard

☐ Simmons

Leak #: 33

☐ Spears

☐ Moody

Street Address: 912 Green Road.

Type of Leak:	Size:	Material:		
Meter ☐	5/8" ☐	8" ☐	30" ☐	Poly ☒
Meter Yoke ☐	3/4" ☒	10" ☐	36" ☐	Copper ☐
Service Line ☒	1" ☐	12" ☐	Other ☐	Galvanized ☐
Valve ☐	2" ☐	16" ☐		PVC ☐
Fire Hydrant ☐	3" ☐	18" ☐		A/C ☐
Main Line ☒	4" ☐	20" ☐		Cast Iron ☐
Other: ☐	6" ☐	24" ☐		Ductile Iron ☐
				Other: ☐

Rating (1-5): 4

☐ Blue Dot on Box

☐ Blue X on Leak Location

Notes:

Service Line or Possibly Main

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day	Leak Location Sketch:
1	•	400	
2	•	3,000	
3	•	8,000	
4	•	15,000	
5	Severe Leak - Repair as soon as possible (20,000+ per day)		