

City/Utility: Oliver Springs



RYE
ENGINEERING PLC

LEAK REPORT

Date: 3-16-20

Crew Chief: ☒ Sheppard

Simmons ☐

Leak #: 5

☐ Spears

Moody ☐

Street Address: 143 Fowler St.

Type of Leak:	Size:	Material:	
Meter ☒ ?	5/8" ☐	8" ☐	30" ☐
Meter Yoke ☒	3/4" ☒	10" ☐	36" ☐
Service Line ☐	1" ☐	12" ☐	Other ☐
Valve ☐	2" ☐	16" ☐	
Fire Hydrant ☐	3" ☐	18" ☐	
Main Line ☐	4" ☐	20" ☐	
Other: ☐	6" ☐	24" ☐	

Material:
Poly ☐
Copper ☐
Galvanized ☐
PVC ☐
A/C ☐
Cast Iron ☐
Ductile Iron ☐
Other: ☐

Rating (1-5): 2

☐ Blue Dot on Box

☐ Blue X on Leak Location

Notes: Leaking IN Box Blue Arrow pointing to Leak

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day
1	•	400
2	●	3,000
3	●	8,000
4	●	15,000
5	Severe Leak - Repair as soon as possible (20,000+ per day)	