

City/Utility: Oliver Springs



RYE
ENGINEERING PLC

LEAK REPORT

Date: 3/26/20

Crew Chief:

☐ Sheppard

☒ Simmons

Leak #: 53

☐ Spears

☐ Moody

Street Address: 660 Hen Valley Rd

Type of Leak:

Meter ☐
Meter Yoke ☐
Service Line ☒
Valve ☐
Fire Hydrant ☐
Main Line ☐
Other: _____

Size:

5/8" ☐ 8" ☐ 30" ☐
3/4" ☒ 10" ☐ 36" ☐
1" ☐ 12" ☐ Other ☐
2" ☐ 16" ☐
3" ☐ 18" ☐
4" ☐ 20" ☐
6" ☐ 24" ☐

Material:

Poly ☒
Copper ☐
Galvanized ☐
PVC ☐
A/C ☐
Cast Iron ☐
Ductile Iron ☐
Other: _____

Rating (1-5): 3

☐ Blue X on Box

☐ Blue X on Leak Location

☒ Blue Arrow Pointing to Leak

Notes: _____

This is calculated at 60 PSI:

Leak Location Sketch:

Rating	Pipe Leak Size	Gallons Lost/Day
1	•	400
2	●	3,000
3	●	8,000
4	●	15,000
5	Severe Leak - Repair as soon as possible (20,000+ per day)	