



Defect Listing

Pipe Segment Refere... A-63_A-62	City Oliver Springs	Street Green Street	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A-63	Total Length 181.4	Year Laid	Shape Circular	Location Details	
DS Manhole A-62	Length surveyed 181.4	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream	Date 20150728	Media label	
OPR N/A	Surveyed By Barry_Rogers	Pre-Cleaning Jetting	Time 08:26	Weather Damp	
OPRI N/A	Certificate Number U-1012-16405	Date Cleaned 20150728	End Time 08:35	Additional Info	

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-63									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
111.5 ft.	Tap Factory Made Active		6		0	<input type="checkbox"/>	9		
178.9 ft.	Water Level				5	<input type="checkbox"/>			
181.4 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A-62									




Image Report 4/Page

Pipe Segment Refere... A-63_A-62	City Oliver Springs	Street Green Street	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH A-63	Total Length 181.4	Year Laid	Shape Circular		Location Details	
DS Manhole A-62	Length surveyed 181.4	Year Renewed	Height 8	Width 8	Pipe Joint...	4




Distance: 0.0 ft. Grade: 0
 Condition: Access Point Manhole
 Remarks: A-63



Distance: 0.0 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Distance: 111.5 ft. Grade: 0
 Condition: Tap Factory Made Active
 Remarks: N/A



Distance: 178.9 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Image Report 4/Page

Pipe Segment Refere... A-63_A-62	City Oliver Springs	Street Green Street	Material Concrete Pipe (non-...		Location C... Light High...	Sewer Use Sanitary
Upstream MH A-63	Total Length 181.4	Year Laid	Shape Circular		Location Details	
DS Manhole A-62	Length surveyed 181.4	Year Renewed	Height 8	Width 8	Pipe Joint...	4



Distance: 181.4 ft. Grade: 0
 Condition: Access Point Manhole
 Remarks: A-62

