



Defect Listing

Pipe Segment Refere... A10-2_A10-1	City Oliver Springs	Street Walker Dr	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A10-2	Total Length 238.6	Year Laid	Shape Circular	Location Details	
DS Manhole A10-1	Length surveyed 238.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4

SPR N/A	MPR N/A	PO Number 4397-03		Customer GRW	
SPRI N/A	MPRI N/A	Work Order 4397-02		Purpose Pre-Rehabilitation Survey	
QSR N/A	QMR N/A	Direction Downstream	Date 20150817	Media label	
OPR N/A	Surveyed By Charlie Gordon	Pre-Cleaning Jetting	Time 10:55	Weather Dry	
OPRI N/A	Certificate Number U-615-07000491		End Time 11:09	Additional Info	
	Date Cleaned 20150817				

Distance	Condition	Cont. Dfct.	Values			Joint	Clock Position		Grade
			1st	2nd	%		At/From	To	
0.0 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A10-2									
0.0 ft.	Water Level				5	<input type="checkbox"/>			
6.0 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
10.6 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	9		
115.4 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	10		
143.9 ft.	Tap Factory Made		6		0	<input type="checkbox"/>	3		
237.7 ft.	Water Level				5	<input type="checkbox"/>			
238.6 ft.	Access Point Manhole				0	<input type="checkbox"/>			
Remarks: A10-1									

Image Report 4/Page


Pipe Segment Refere...	City	Street	Material	Location C...	Sewer Use
A10-2_A10-1	Oliver Springs	Walker Dr	Concrete Pipe (non-...	Light High...	Sanitary
Upstream MH A10-2	Total Length 238.6	Year Laid	Shape Circular	Location Details	
DS Manhole A10-1	Length surveyed 238.6	Year Renewed	Height	Width	Pipe Joint...
			8	8	4




Distance: 0.0 ft. Grade: 0
 Condition: Access Point Manhole
 Remarks: A10-2



Distance: 0.0 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Distance: 6.0 ft. Grade: 0
 Condition: Tap Factory Made
 Remarks: N/A




Distance: 10.6 ft. Grade: 0
 Condition: Tap Factory Made
 Remarks: N/A

Image Report 4/Page


Pipe Segment Refere... A10-2_A10-1	City Oliver Springs	Street Walker Dr	Material Concrete Pipe (non-...	Location C... Light High...	Sewer Use Sanitary
Upstream MH A10-2	Total Length 238.6	Year Laid	Shape Circular	Location Details	
DS Manhole A10-1	Length surveyed 238.6	Year Renewed	Height 8	Width 8	Pipe Joint... 4



Distance: 115.4 ft. Grade: 0
 Condition: Tap Factory Made
 Remarks: N/A



Distance: 143.9 ft. Grade: 0
 Condition: Tap Factory Made
 Remarks: N/A



Distance: 237.7 ft. Grade: 0
 Condition: Water Level
 Remarks: N/A



Distance: 238.6 ft. Grade: 0
 Condition: Access Point Manhole
 Remarks: A10-1

